Mount D435(i) Realsense camera on the robot using 1/4-20 x 3/8" screw.



First install mounting screw.

Then fasten the camera.