Connect the Li-Po battery to the motor driver and power on the Raspberry Pi if you haven't done so already. It's perfectly fine for the Raspberry Pi to be powered simultaneously through the motor driver (battery power supply) and a Type-C DC power supply.